

Worcester Polytechnic Institute DigitalCommons@WPI

Morgan Documents

Morgan Construction Company records

July 2014

Electric Billet Shears

Bill Murray

Follow this and additional works at: <http://digitalcommons.wpi.edu/ms077morgan-docs>

Recommended Citation

Murray, Bill, "Electric Billet Shears" (2014). *Morgan Documents*. Book 173.
<http://digitalcommons.wpi.edu/ms077morgan-docs/173>

This Article is brought to you for free and open access by the Morgan Construction Company records at DigitalCommons@WPI. It has been accepted for inclusion in Morgan Documents by an authorized administrator of DigitalCommons@WPI.



ROLLING MILLS
MORGOL BEARINGS
WIRE MACHINERY
COMBUSTION CONTROLS

MORGAN CONSTRUCTION COMPANY

Engineers and Manufacturers

CABLE "MORGAN"

15 BELMONT STREET

WORCESTER 5, MASSACHUSETTS, U.S.A.

Manchester Office
1 Central Street
Manchester 2
ENGLAND

7 October 1964

Mr. Stephen Ordog
Morgan Construction Company
15 Belmont Street
Worcester
MASSACHUSETTS 01605
U.S.A.

Via AIR MAIL

Dear Stephen: Electric Billet Shears

Thank you for your interesting letter of the 1 October, writing on the subject of tail end disposal is difficult in that there are several ways that we run into trouble with tail ends hanging up on the bottom shear blade and tail rod, or the bottom blade and the swinging roller, or the bottom blade and the last roller before the shear.

In those hanging up positions the common factor is the bottom blade and I agree with your comment in the last paragraph on page 2 of your letter of the 1 October, if the bottom blade takes another cut and does not stop in the down position the tail end should fall down the chute, or at least it has less chance of causing trouble.

Let us take the case of a tail end of less than 4' - 3", the centres length between the last roller and the swinging roller, this will drop down and may go to the chute or the first end may rest on the bottom blade holder and the back end on the tail rod. In this case, another revolution of the shear should see the tail end down the chute and all is well.

Now take a tail end of say 6 to 7 feet length which with speed will reach the swing roller, as the back end leaves the last roller before the shear we have 21 to 33 inches beyond the swing roller centre, but as the back end leaves its supporting roller it falls down on to the bottom blade holder and the tail end is now resting on the swing roller and the bottom blade. The idea of a top pinch roller on the swing roller was to pull such a length onto the runout table and it is this sort of length Rheinhausen want to salvage.

TO	ACT	INF
ERC		
MG		
JHH		
RJH		
WJH		
RK		
WWK		
ACM		
CSM		
ERM	✓	
GHM		
MM		
PASH		
PMM	✓	
SO	✓	
AP		
DS		
WHW		
NAW		
HHW		
RY		
MS		
PIT		
G.F.		

MORGAN CONSTRUCTION COMPANY

PAGE

2

Mr. S. Ordog

DATE 7 Oct 64

I therefore think that if Worcester think such a contraption will pull a 6 feet length onto the runnout table we should give Rheinhausen a sketch of it and let them make it themselves, Morgan has no responsibility as far as tail end salvage is concerned, this is a function of the ever increasing price of billets and the more efficient welding equipment.

At the same time we should use Ed Murrah's idea of making another air cutting revolution after the last billet cut. In other words, if a pinch roller can be made to pull 6 feet lengths on to the runnout table and we use Ed's idea, we should cover all points.

You probably have grave doubts about the practicability of such a pinch roller, I must admit I have myself, particularly, a non-driven one.

If you have further thoughts on this point will you write me at Siemag, Dusseldorf.

Kind regards,

Sincerely

B. J.

P. J. W.

WM/swf
for Min. List & ACM
cc L. Petereit - Siemag